Ovation™ Interim Publication Update

Date: 7/01
IPU No. 210

PUBLICATION TITLE

Ovation Error Codes and Messages
Revision 0, July 2001

Publication No. R3-1145

This publication update contains the following additions and changes:

- Revised Table A-2 of I/O Status Values. This table contains Parameter 5 errors related to Controller Fault Code 66.

Westinghouse Process Control, Inc. Proprietary Class 2C

Replace Table A-2 with the following table:
Page A-2

Table A-2. I/O Status Values

Bit	Definition
0x0000 or 0x8000	Local: No response from module
0x0800 or 0x8800	Remote: Echo: No response
0x0a00 or 0x8a00	Remote: Node: No response
0x0e00 or 0x8e00	Remote: Transmit collision[1]
0x2000 or 0xa000	Local: Bad CRC
0x2800 or 0xa800	Remote: Echo: Bad CRC[1]
0x2a00 or 0xaa00	Remote: Node: Bad CRC
0x2e00 or 0xae00	Remote: I/O control register changed
0x4000 or 0xc000	Local: Module in attention
0x4c00 or 0xcc00	Remote: Node in attention
0x4e00 or 0xce00	Remote: PCRR internal error
0x6000 or 0xe000	Success
0x6200 or 0xe200	Remote: Echo: Wrong SRC[1]
0x6400 or 0xe400	Remote: Node: Wrong SRC
0x6800 or 0xe800	Remote: Echo: Wrong DST[1]
0x6a00 or 0xea00	Remote: Node: Wrong DST
0x6c00 or 0xec00	Remote: Node: Invalid response
0x0180 or 0x8180	IOIC board not in control
0x0190 or 0x8190	Q-line DIOB volts bad
0x00a0 or 0x80a0	Illegal access type
0x00b0 or 0x80b0	Illegal hardware address
0x00c0 or 0x80c0	Point not scanned yet
0x01f0 or 0x81f0	Third-party I/O Driver Error (for example, invalid GE Mark V/VI tables)
[1] Consider updating PCRR (3A99190G01) Board to Revision 14 (per DEO 57211).	

Westinghouse Process Control, Inc. Proprietary Class 2C