HIMA F8640

H41/H51 Legacy Module

01 / PREPARATION, RESTORATION AND ACCEPTANCE

Planning aid for HIMA F8640. Use the applicable equipment instructions and authorized site procedure for physical work and test execution. The checks below apply the documented model distinctions; they do not introduce undocumented device limits.

Controlled work sequence

01 / Capture the legacy configuration

Associate the F8640 marking and 98 1864002 part number with the existing H41/H51 cabinet record. Preserve the installed position and connected equipment references before planning removal.

02 / Separate replacement from conversion

A like-identity service job and a change to a different module are different work scopes. The lifecycle row does not name a successor, so do not treat a model-number change as a routine swap.

03 / Obtain the installation-specific instructions

Use the controlled H41/H51 documentation for isolation, connector handling and restoration. This lifecycle-based guide supplies no live-removal permission, wiring pinout or test voltage.

04 / Review the as-left evidence

The release record should identify the actual installed part and the results required by the approved system test. Keep any changed part designation visible in the engineering review.

Model-specific acceptance checks

Subject	Expected evidence
Identity reconciliation	F8640 and 98 1864002 agree with the work scope.
Host-system reference	The retained equipment record identifies the H41/H51 installation.
Restored system response	The authorized system test has its required recorded outcome.

More Apter Power catalog references

Catalog navigation only; no compatibility or substitution implied.

HIMA F8650X | View product page

HIMA F8652X | View product page

HIMA F8640

H41/H51 Legacy Module

02 / EXCEPTION HANDLING AND REFERENCE SUPPORT

Same dates, different module

F8640 and F8641 share discontinuation and end-of-life dates in the register. Those dates do not establish an interchangeable hardware pair.

An unlabeled replacement offer

Ask for the actual marking and revision record. Do not identify a loose module from appearance or from the F86xx family alone.

If a check fails

Identity reconciliation: Stop the match if the part marking differs.

Host-system reference: Resolve the host record before assigning another platform.

Restored system response: Use system diagnostics; no undocumented F8640 test limits are supplied here.

Technical reference record

List of discontinued products | Rev. 18, August 2012 - Page 6 of 6; F 8640 row. Historical lifecycle evidence, not a current availability statement.

Related Apter Power catalog references

Catalog navigation only. These entries do not establish compatibility, substitution or approval of a changed installation.

HIMA F8651X | View HIMA F8651X page

HIMA F8650E | View HIMA F8650E page

HIMA F8641 | View HIMA F8641 page

CONTACT APTER POWER

WHATSAPP / PHONE +86 180 3023 5313

EMAIL sales13@apterpower.com

WEBSITE www.apterpower.com

Send the exact model, quantity and requested condition for a quotation.

F8640