Foxboro P0904AK

System architecture

A GCIO installation separates the workstation link from the keyboard links. A dual arrangement adds an interconnection between primary and secondary interfaces. Keeping these three paths identifiable makes an annunciator fault easier to localize without disturbing unrelated display wiring.

Technical data

Parameter	Value
Interface	GCIO
Touchscreen interface	Not included
Keyboard cable	P0800MW
Dual-GCIO interconnection	P0970HV
Annunciator keyboard	P0903CV
Annunciator/numeric keyboard	P0903CW
Dual-GCIO keyboard capacity	Up to 4 keyboards across 2 GCIO units

Interpret the operating symptom

Observation	Engineering check
One keyboard is inactive	Inspect its assigned keyboard cable and connection before disturbing the other keyboard.
Secondary group is unavailable	Check the interconnection between the primary and secondary GCIO units and the paths serving the affected group.
Monitor touch is unavailable	Investigate the separate touch arrangement; the P0904AK does not provide that interface.

Other Foxboro catalogue pages — separate products

Foxboro FBM207C P0917GY

Foxboro CP40B