General Electric 531X307LTBAKG1

Installation & Commissioning | field workflow

Use this guide to prepare, fit, test and document the offered 531X307LTBAKG1 within its actual installed system.

Exact offered identity	531X307LTBAKG1
Engineering role	LAN I/O Terminal Board
Installed-system reference	GE DC2000 drive LAN I/O

Before work starts

GEH-6005 describes the 531X307LTB G1 board family, including eight inputs and seven relay outputs. The supplied KG1 revision is identified by its complete board marking; verify its installed wiring and revision before applying family-level ratings.


Record first

Send the complete 531X307LTBAKG1 marking, installed revision, quantity and system configuration with your enquiry.

Work package

Board design	531X307LTB LAN I/O terminal board
Board group	G1 family; complete KG1 revision marking
Control inputs	Eight labeled IN1-IN8 on the observed board
Relay outputs	Seven labeled OT1-OT7 on the observed board

Engineering path




02 Pre-installation readiness

STEP	ACTION	ACCEPTANCE
01	Isolate every field source	De-energize drive and separately supplied field circuits. Confirm safe voltage at input and output terminal rows before handling the board.
02	Preserve terminal identity	Label conductors at IN1–IN8 and OT1–OT7; record polarity, commons and external protection before disconnecting any wire.
03	Control output loading	The G1 family Form C contacts are non-fused. Check the connected load and provide external protection appropriate to the actual circuit.
04	Separate ribbon and power	Route the controller ribbon connection away from power conductors; capacitive coupling or leakage can hold inputs in an unintended ON state.

Companion and host check

Confirm the terminal board and any mating ribbon connectors in the quotation; field cables, external relays and the drive controller are separate unless listed.

Review sequence



03 Fit and interface

Operator and interlock inputs

Land documented pushbutton, limit and permissive contacts on the assigned IN points, preserving the drive's input logic and voltage scheme.

Contactor and alarm outputs

Use the seven relay-output positions for specified drive commands or indications within the connected load and external protection limits.

Pilot-relay interface

Connect the LTB pilot circuits to the intended higher-current relay board only when the cabinet design includes that arrangement.


Drive-service replacement

Exchange the board against the complete KG1 marking and as-built terminal map, then prove each used input and output from field device to controller.

I/O relationship

The 531X307LTB G1 design interfaces DC2000 control electronics with field switches, pilot devices and relay circuits. Match the observed IN1-IN8 and OT1-OT7 terminals to the original wiring drawing.

Review sequence



04 Commission and prove

STEP	ACTION	ACCEPTANCE
01	Match the KG1 board	Compare full board marking, connector orientation and revision with the installed hardware. Do not assume another LTB suffix is drop-in compatible.
02	Prove inputs and outputs	After reconnection, stimulate each used field input and command each assigned output in a safe test state, recording controller indication and actuator response.
03	Record the functional result	Verify ribbon connections and every used IN/OT terminal. Under a safe drive state, prove the external device, terminal point, controller indication and commanded output path one by one.

Circuit limits

The family manual specifies non-fused Form C outputs and input/terminal limits. Confirm the exact KG1 board revision and connected load before applying the family ratings; protect external circuits separately.

05 Handover and replacement record

How should input voltage be checked for 531X307LTBAKG1?	The LTB family manual provides AC and DC input ranges, but the actual field voltage must be taken from the cabinet schematic. Verify every input source and common before reconnecting the KG1 terminals.

Why should ribbon wiring for 531X307LTBAKG1 be separated from power cables?	The GE manual warns that capacitive coupling and leakage can make an I/O input remain ON. Preserve the 26-conductor interconnect route, keep it away from power wiring and investigate any input that does not drop out.
Can another 531X307LTB revision replace 531X307LTBAKG1 without review?	Do not infer interchangeability from the shared base name. Compare the complete KG1 board identity, connector positions, input circuits and output wiring against the installed drive before substitution.

Acceptance note

Log the fitted marking, firmware or board revision where present, wiring changes, test results and the approved plant configuration. GEH-6005 describes the 531X307LTB G1 board family, including eight inputs and seven relay outputs. The supplied KG1 revision is identified by its complete board marking; verify its installed wiring and revision before applying family-level ratings.

Discuss the complete model and fitted revision with Apter Power.
sales13@apterpower.com | +86 18030235313

Technical basis: GE DC2000 Digital Adjustable Speed Drive Instruction Manual, GEH-6005; original GE text copy

Other General Electric references

Catalog navigation only; confirm each complete model for its own installation.

General Electric DS200FSAAG1A	View product reference
General Electric DS200FSAAG1ABA	View product reference
General Electric DS200FSAAG2ABA	View product reference