HIEE300025R2 VDA330 A02

01 / Installed system and risk controls

ABB HIEE300025R2 VDA330 A02 is a multi-connector interface circuit board. The offered assembly carries HIEE300025R2 and VDA330 A02 and presents two rows of multiple D-sub connectors with numbered positions for its installed cabinet position.

Rack and field boundary

The board belongs to an installed ABB cabinet or rack; the host slot, external cable harness and powered field circuits define the complete installation.

Before returning the system to service

Isolate before handling

Follow the cabinet lockout and discharge procedure before touching the open circuit board or rear mating contacts.

Capture the baseline

Record every D-sub cable identifier and front-panel socket position before removal; physically identical plugs can serve different circuits.

Control electrostatic damage

Handle the board by its faceplate or edges and use the site-approved ESD work area and packaging.

Inspect both mating sides

Check front sockets, rear pins, retaining hardware and guide rails for bent contacts or contamination.

Record the installed configuration

Baseline

Record both ABB label parts, cabinet position, connector orientation and visible switch settings before removal.

Cable plan

Record every D-sub cable identifier and front-panel socket position before removal; physically identical plugs can serve different circuits.

Mating review

Compare front and rear contact condition with the removed board before seating and fastening the replacement.

HIEE300025R2 VDA330 A02

02 / Commission and hand over

What identifies the exact ABB HIEE300025R2 VDA330 A02 assembly during replacement?

Use the complete HIEE300025R2 and VDA330 A02 marking together with the photographed faceplate and rear connector arrangement. A shortened family code does not establish the same revision or circuit role.

How should cables be recorded before removing ABB HIEE300025R2 VDA330 A02?

Record every D-sub cable identifier and front-panel socket position before removal; physically identical plugs can serve different circuits. Mark both cable ends and the original socket or terminal position so reassembly is traceable.

Does the visible connector arrangement on ABB HIEE300025R2 VDA330 A02 define its pinout?

The connector pattern is visible; signal direction, pinout and protocol are not established by the exterior marking alone. Use the installed ABB wiring drawing and verify each lead before connecting field power.

Can another ABB board with a similar faceplate replace HIEE300025R2 VDA330 A02?

Match R2 and A02 as a complete pairing and compare the host slot and cable schedule; connector shape alone does not prove interchangeability. Check the full code, board revision, rear mating interface and host configuration before considering an alternative.

What should be inspected on the rear of ABB HIEE300025R2 VDA330 A02?

Inspect two long multipin rear connectors, guide alignment and contact condition. A bent or contaminated mating pin can create an intermittent fault even when the front wiring appears correct.

Which ABB HIEE300025R2 VDA330 A02 settings or configuration should be preserved?

Record the host slot, any visible switch positions, board-revision labels and the connected circuit mapping before removal. Restore only settings supported by the installed system documentation.

Close-out evidence

Record the installed wiring, configuration and as-left functional checks under the site change record.

Technical basis: ABB HIEE300025R2 / VDA330 A02 markings and visible connector layout on supplied unit photographs.

Technical enquiry

sales13@apterpower.com | +86 18030235313