


MANUFACTURER-SOURCE TECHNICAL REFERENCE

Bently Nevada 200350-12-00-CN

Installation Guide

case-mounted piezoelectric accelerometer



DOCUMENT SCOPE

Apter Power product reference prepared from product-specific Bently Nevada technical information. Confirm the complete product identity and installed-system requirements before use. No product photograph is included.

Product / lookup identity	Bently Nevada 200350-12-00-CN
Reference number	200350-12-00-CN
Document basis	Bently Nevada technical documents listed on page 3



Product page

<https://www.apterpower.com/Bently-Nevada/200350-12-00-cn>

Apter Power contact

sales13@apterpower.com | +86 180 3023 5313

Workflow and system context

Bently Nevada 200350-12-00-CN is a case-mounted piezoelectric accelerometer with an M8 x 1.25 adhesive stud mount and 100 mV/g sensitivity tolerance. Use it only in the matched Bently Nevada machinery-monitoring installation and verify the complete product code, associated hardware, mounting and wiring before service.

01	System Inputs: case-mounted piezoelectric accelerometer
02	Processing: Bently Nevada 200350-12-00-CN is a case-mounted piezoelectric accelerometer with an M8 x 1.25 adhesive stud mount and 100 mV/g sensitivity tolerance.

Published context and boundaries

01	Confirm the adhesive-stud preparation, cable interface, excitation supply and installed monitoring system before installation.
02	Verify model 200350-12-00-CN and the complete order code on the physical label before use.
03	Match every 200350-12-00-CN connector, terminal, cable and companion assembly before moving field wiring.

Verification and release checks

01	Verify model 200350-12-00-CN and the complete order code on the physical label before use.
02	Confirm the adhesive-stud preparation, cable interface, excitation supply and installed monitoring system before installation.
03	Match every 200350-12-00-CN connector, terminal, cable and companion assembly before moving field wiring.
04	Back up the applicable controller, monitor, HMI or I/O configuration before replacing 200350-12-00-CN.
05	Isolate energy and follow the approved site safety procedure before handling 200350-12-00-CN.
06	Follow ESD controls and protect 200350-12-00-CN connectors and printed-circuit assemblies during handling.

Identity and release controls

Verification Status	Verified Product Reference
---------------------	----------------------------

Official Bently Nevada sources

200350 and 200355 Accelerometers Datasheet	https://dam.bakerhughes.com/m/592c656c5035efa8/original/200350-and-200355-Accelerometers-Datasheet-164804-pdf.pdf
--	---