

Siemens 6EP1333-2BA00

SITOP Power Supply

Rail-mounted switched-mode power supply providing a regulated 24 V DC, 5 A output for industrial control loads.

Job objective

Replace, install or verify the exact module without changing unrelated wiring, configuration, dimensions, weight or other stored product data.

Safe-work boundary

Identify Match the complete model and every suffix or secondary code.	Isolate Apply the plant-approved electrical and process isolation procedure.
Preserve Back up configuration and photograph all connections.	Control Use ESD protection and revision-controlled documentation.

Required evidence before work

Nameplate photo; slot/rack record; connector map; project backup where applicable; fault history; approved acceptance procedure.

Readiness checklist

Exact identity	Siemens 6EP1333-2BA00 matches the work order and physical unit
System position	Rack, slot and functional assignment are recorded
Configuration	Parameters, firmware or project data are backed up when applicable
Connections	Every cable, terminal, jumper and shield is labeled
Condition	Connector, board and packaging condition are inspected
Test plan	Expected states and acceptance evidence are agreed

Interface preparation

L1 / N	AC input
PE	Protective earth
AC 120 V jumper	Input-range configuration
L+ / M	Regulated DC output

Controlled replacement workflow

1	Confirm isolation and absence of hazardous energy
2	Compare old and replacement identities and revisions
3	Photograph and label all connections
4	Remove the existing module using ESD-safe handling
5	Inspect slot, connector, grounding and cooling path
6	Install the exact replacement without forcing connectors
7	Restore cables, jumpers and settings from the controlled record
8	Perform a final visual and continuity check before energization

STOP POINT

Do not energize if the model, slot, connector orientation, grounding, jumper state or documented system assignment is unresolved.

Staged return to service

Stage	Action	Acceptance
Stage 1	Visual inspection and isolation release	Expected controlled result
Stage 2	Apply control power under observation	Expected controlled result
Stage 3	Confirm module recognition or status	Expected controlled result
Stage 4	Verify communication and affected signal paths	Expected controlled result
Stage 5	Exercise the documented function	Expected controlled result
Stage 6	Archive measured results and as-left configuration	Expected controlled result

Product-specific acceptance focus

1 Keep the documented vertical orientation with terminals at the bottom.	2 Maintain 50 mm free space above and below for natural cooling.
3 Use conductors and tightening torque within the documented terminal limits.	4 Measure the 24 V DC output before reconnecting sensitive loads.

Fault isolation and final record

1	Unexpected state: stop and capture evidence
2	Recheck identity, power, slot and connectors
3	Compare configuration and revision records
4	Test surrounding system before condemning the module
5	Restore a safe state and document the outcome

Apter Power handover record

Model identity	Keep the complete Siemens model code and every suffix in purchasing, installation and acceptance records.
Verification boundary	Confirm the physical nameplate, installed position and revision-controlled project documents before field work.
Apter Power support	Use the contact details and Apter Power website links in this document for product and sourcing support.

Related Apter Power references	Scope note
Siemens 39SDM024DCCBN 16101-174/8	Portfolio reference only; verify compatibility independently.
Siemens 16101-174/10	Portfolio reference only; verify compatibility independently.



Commissioning support sales7@apterpower.com +86 180 3017 5807 www.apterpower.com