Product dashboard

Bently Nevada 128276-01F 131151-01 is a supplied two-part rack-accessory marking that includes the documented 131151-01 half-height blank front panel cover. The complete marking and included screws must remain together when closing an unused half-height rack position.

Exact model	Product type	System family	Functional role
128276-01F 131151-01	Half-Height Blank Front Panel Assembly	3500 System Rack	Rack Accessory

PARAMETER	DOCUMENTED VALUE
Complete supplied marking	128276-01F 131151-01
Documented cover part	131151-01
Accessory type	Half-height blank front panel cover
Supplied quantity	One cover
Included hardware	Screws
Rack family	3500 System Rack
Position check	Unused half-height front position
Acceptance	Cover seating and rack-face inspection

Release basis: verify the exact identity, retained host relationship, connected interfaces and controlled functional result.

CONTACT APTER POWER

WHATSAPP / PHONE +86 180 3023 5313

EMAIL sales13@apterpower.com

WEBSITE www.apterpower.com

128276-01F 131151-01

System overview

128276-01F 131151-01 preserves the intended front-panel arrangement of a matched 3500 rack position, with the full supplied marking and included hardware checked before installation.

Installed-system renewal

Restores the documented 128276-01F 131151-01 position while keeping the approved host and interfaces.

Controlled maintenance

Supports as-found recording, safe isolation and exact connection restoration.

Compatibility review

Compares the full marking, host, connectors, settings and companion hardware.

Commissioning evidence

Records diagnostics and a controlled functional test of covering and protecting an unused half-height front-panel position.

SYSTEM POSITION	RECORD
Installed identity	128276-01F 131151-01

CONTACT APTER POWER

WHATSAPP / PHONE +86 180 3023 5313

EMAIL sales13@apterpower.com

WEBSITE www.apterpower.com

128276-01F 131151-01

Technical data map

PARAMETER	VERIFIED VALUE
Complete supplied marking	128276-01F 131151-01
Documented cover part	131151-01
Accessory type	Half-height blank front panel cover
Supplied quantity	One cover
Included hardware	Screws
Rack family	3500 System Rack
Position check	Unused half-height front position
Acceptance	Cover seating and rack-face inspection

CONTROL BAND	VERIFICATION RECORD
Identity	Exact model and complete label
Mechanical	Form, seating and retention
Interfaces	Power, wiring, communication and protection
Configuration	Settings, project and revision
Release	covering and protecting an unused half-height front-panel position

Technical evidence record: 141525 Rev. M

CONTACT APTER POWER

WHATSAPP / PHONE +86 180 3023 5313

EMAIL sales13@apterpower.com

WEBSITE www.apterpower.com

128276-01F 131151-01

Applications and precautions

1. Confirm the complete 128276-01F 131151-01 marking before work.
2. Place the affected equipment in its approved maintenance state.
3. Isolate connected energy and prove the circuit safe.
4. Photograph the slot, wiring, connectors and settings before removal.
5. Match every documented interface and companion component.
6. Restore mechanical retention, shielding and protective earth.
7. Review hardware, network and controller diagnostics after energization.
8. Functionally verify covering and protecting an unused half-height front-panel position before service release.

Complete each check against the installed record; hold release when any identity, connection, configuration or diagnostic result differs.

CONTACT APTER POWER

WHATSAPP / PHONE	+86 180 3023 5313
EMAIL	sales13@apterpower.com
WEBSITE	www.apterpower.com

128276-01F 131151-01

Buyer and engineering FAQ

What does 128276-01F 131151-01 identify?

128276-01F 131151-01 identifies the half-height blank front panel assembly used for covering and protecting an unused half-height front-panel position.

Which installed system must 128276-01F 131151-01 match?

Match 128276-01F 131151-01 to the recorded 3500 System Rack host, position and companion hardware.

Which markings must be checked on 128276-01F 131151-01?

Verify the complete 128276-01F 131151-01 text and every suffix, revision or assembly marking on the supplied item.

What should be recorded before removing 128276-01F 131151-01?

Record the slot, connectors, cable labels, switches, parameters, adjacent hardware and diagnostic state.

Related Apter Power pages

- Bently Nevada 991 01 XX 01 01 MOD 284318 01 — View product page
- Bently Nevada 990 08 XX 01 00 MOD 165353 01 — View product page
- Bently Nevada 74712 06 12 04 04 — View product page

CONTACT APTER POWER

WHATSAPP / PHONE	+86 180 3023 5313
EMAIL	sales13@apterpower.com
WEBSITE	www.apterpower.com

128276-01F 131151-01