Product dashboard

Emerson KJ4010X1-BF1 12P0831X062 is a left-side carrier extender for a documented DeltaV M-series horizontal-carrier assembly. Its exact part-number revision, orientation and adjacent carrier relationship must remain matched to the installed system.

Exact model	Product type	System family	Functional role
KJ4010X1-BF1 12P0831X062	DeltaV Left Carrier Extender	DeltaV M-series Horizontal Carriers	Carrier Extender

PARAMETER	DOCUMENTED VALUE
Exact model	KJ4010X1-BF1 12P0831X062
Hardware role	Left carrier extender
Platform	DeltaV M-series
Subsystem	Horizontal carrier architecture
Orientation	Left side
Revision identity	12P0831X062
Installation basis	Match recorded adjacent carrier and cable direction
Service boundary	De-energize before changing carrier interconnections

Release basis: verify the exact identity, retained host relationship, connected interfaces and controlled functional result.

CONTACT APTER POWER

WHATSAPP / PHONE +86 180 3023 5313

EMAIL sales13@apterpower.com

WEBSITE www.apterpower.com

KJ4010X1-BF1 12P0831X062

System overview

Within a DeltaV M-series carrier row, KJ4010X1-BF1 12P0831X062 continues the LocalBus architecture from the recorded left-side extender position.

Exact-position replacement

Matches KJ4010X1-BF1 12P0831X062 to the recorded host, position and companion hardware before changeout.

Interface restoration

Rebuilds the documented power, signal, keying and protective interfaces for KJ4010X1-BF1 12P0831X062.

Configuration-controlled service

Restores settings and assignments from the approved record rather than a neighboring module.

Acceptance and handover

Confirms diagnostics and the controlled functional response of KJ4010X1-BF1 12P0831X062 before release.

SYSTEM POSITION	RECORD
Installed identity	KJ4010X1-BF1 12P0831X062
Host relationship	DeltaV M-series Horizontal Carriers
Controlled function	left-side extension of the documented horizontal carrier row

CONTACT APTER POWER

WHATSAPP / PHONE +86 180 3023 5313

EMAIL sales13@apterpower.com

WEBSITE www.apterpower.com

KJ4010X1-BF1 12P0831X062

Technical data map

PARAMETER	VERIFIED VALUE
Exact model	KJ4010X1-BF1 12P0831X062
Hardware role	Left carrier extender
Platform	DeltaV M-series
Subsystem	Horizontal carrier architecture
Orientation	Left side
Revision identity	12P0831X062
Installation basis	Match recorded adjacent carrier and cable direction
Service boundary	De-energize before changing carrier interconnections
Acceptance	Carrier power, LocalBus continuity and module recognition

CONTROL BAND	VERIFICATION RECORD
Identity	Exact model and complete label
Mechanical	Form, seating and retention
Interfaces	Power, wiring, communication and protection
Configuration	Settings, project and revision
Release	left-side extension of the documented horizontal carrier row

Technical evidence record: Emerson-authored DeltaV installation and horizontal-carrier documentation

CONTACT APTER POWER

WHATSAPP / PHONE +86 180 3023 5313

EMAIL sales13@apterpower.com

WEBSITE www.apterpower.com

KJ4010X1-BF1 12P0831X062

Applications and precautions

1. Confirm the complete KJ4010X1-BF1 12P0831X062 marking and documented hardware role before work.
2. Place the connected process and controller hardware in the approved maintenance state.
3. Record the host position, companion parts, cable direction, terminal assignments and active configuration.
4. Isolate every documented power, signal and stored-energy source before disconnecting hardware.
5. Protect keyed connectors, electronic contacts and labeled field conductors during handling.
6. Restore only the recorded power, wiring, grounding, shielding and configuration arrangement.
7. Energize in a controlled sequence and review module, carrier, controller and field diagnostics.
8. Function-test left-side extension of the documented horizontal carrier row and retain the acceptance record before service release.

Complete each check against the installed record; hold release when any identity, connection, configuration or diagnostic result differs.

CONTACT APTER POWER

WHATSAPP / PHONE	+86 180 3023 5313
EMAIL	sales13@apterpower.com
WEBSITE	www.apterpower.com

KJ4010X1-BF1 12P0831X062

Buyer and engineering FAQ

What is the documented role of KJ4010X1-BF1 12P0831X062?

It is identified as a deltav left carrier extender used for left-side extension of the documented horizontal carrier row.

Why must the complete KJ4010X1-BF1 12P0831X062 identity be retained?

The full model and suffix distinguish the installed execution from similar-looking revisions and related hardware.

Which value is documented for KJ4010X1-BF1 12P0831X062 hardware role?

The verified product record gives hardware role as Left carrier extender.

How is platform specified for KJ4010X1-BF1 12P0831X062?

The verified product record gives platform as DeltaV M-series.

Related Apter Power pages

- Related industrial automation product
- Related industrial automation product
- Related industrial automation product

CONTACT APTER POWER

WHATSAPP / PHONE	+86 180 3023 5313
EMAIL	sales13@apterpower.com
WEBSITE	www.apterpower.com

KJ4010X1-BF1 12P0831X062