HIMA F8640

H41/H51 Legacy Module

01 / DOCUMENTED IDENTITY AND ENGINEERING DISTINCTIONS

F8640 is recorded in the H41/H51 lifecycle register under part number 98 1864002. Its documented identity and service-history dates are the starting point for evaluating a legacy spare; a neighboring F86xx number is not a replacement specification.

H41/H51 installation → F8640 / 98 1864002 → Exact-record service review

Published product facts

System family	H41/H51
Register designation	F 8640
Part number	98 1864002
Discontinuation date	1 April 2000
End-of-life date	31 March 2010
Named alternative	None in this register row

Application and selection

A lifecycle entry is not an electrical data sheet

The register establishes the system family, part identity and historical dates. It does not provide a supply rating, connector assignment, processor speed or memory capacity for F8640.

No successor is named for this row

The absence of a listed alternative is not an approval to use another H41/H51 or HIQuad module. A proposed conversion needs its own technical basis.

The full part number matters

Use 98 1864002 with the F8640 designation when matching records. The F8641 entry has a different part number even though its lifecycle dates are the same.

More Apter Power catalog references

Catalog navigation only; no compatibility or substitution implied.

HIMA F8650X | View product page

HIMA F8652X | View product page

HIMA F8640

H41/H51 Legacy Module

Model-specific engineering case

For a cabinet recorded as using F8640, first reconcile the installed marking with part number 98 1864002. A supplier offer for an adjacent model should remain a separate proposal until its system application and connections have been established. Historical end-of-life status alone does not describe the condition of a particular spare.

Technical reference record

List of discontinued products | Rev. 18, August 2012 - Page 6 of 6; F 8640 row. Historical lifecycle evidence, not a current availability statement.

Related Apter Power catalog references

Catalog navigation only. These entries do not establish compatibility, substitution or approval of a changed installation.

HIMA F8641 | View HIMA F8641 page

HIMA F8650E | View HIMA F8650E page

HIMA F8651X | View HIMA F8651X page

CONTACT APTER POWER

WHATSAPP / PHONE +86 180 3023 5313

EMAIL sales13@apterpower.com

WEBSITE www.apterpower.com

Send the exact model, quantity and requested condition for a quotation.

F8640