# HIMA K9203A

Monitored Fan Unit



K9203A combines a three-fan insert assembly with fan-run monitoring. The accessory overview confirms those features but does not define a complete electrical or airflow performance envelope.

## Exact-model specification register

| | |
|---|---|
| **Assembly form** | Insert fan unit |
| **Fan arrangement** | Three axial fans |
| **Monitoring feature** | Fan-run monitor |
| **Exact identity** | K9203A, including the A suffix |

## Reading the technical distinctions

| Entry | Documented meaning | Boundary |
|---|---|---|
| **K9203A** | Insert unit; three axial fans; fan-run monitor | This product |
| **K9202B** | Cabinet unit; two axial fans; fan-run monitor | Different assembly |
| **K9212** | Axial fan module for rack installation | Different product description |
| **Monitor feature** | Fan-run monitoring is specified | Alarm logic and delays require detailed documentation |

The comparison entries identify different roles or versions. They are not a bill of compatible replacements, and the values for one component are not transferred to another.

## More Apter Power catalog references

Catalog navigation only; no compatibility or substitution implied.

HIMA F8651E | View product page

HIMA H7506 | View product page

# HIMA K9203A

Monitored Fan Unit



### Does the three-fan count establish K9203A cooling performance?

No airflow, pressure, speed or cabinet heat-load limit is given in the reviewed entry. The count describes the assembly, not its full thermal performance.

### Why must the A suffix in K9203A be retained?

K9203A is the exact model supported by this accessory listing. A base-number or other-suffix product needs its own evidence and should not be silently substituted.

### Is visible fan rotation sufficient to accept the K9203A monitoring function?

No. Rotation is a physical observation, while fan-run monitoring is a separately documented feature. Acceptance of the installed indication path needs the approved normal and fault checks for the actual cabinet. The catalog supplies no universal alarm delay or status-contact value.

## Technical reference record

Technical overview | Safety platform and products, reviewed 23 October 2026 - Accessories section; K9203A with K9202B and K9212 as explicitly separated comparisons.

## Related Apter Power catalog references

Catalog navigation only. These entries do not establish compatibility, substitution or approval of a changed installation.

HIMA K9203 | View HIMA K9203 page

HIMA M3421 | View HIMA M3421 page

HIMA F6705 | View HIMA F6705 page

**CONTACT APTER POWER**

WHATSAPP / PHONE +86 180 3023 5313

EMAIL sales13@apterpower.com

WEBSITE www.apterpower.com

Send the exact model, quantity and requested condition for a quotation.

K9203A