Installation Verification Guide

MC-PSIM11 51304362-350

Pre-installation identity and document checks

An Apter Power verification checklist for MC-PSIM11 51304362-350. Apply the manufacturer instructions and approved site procedure for actual work; this is not a wiring or commissioning manual.

01 Retain both identifiers

Use MC-PSIM11 51304362-350 on the work order and quotation. Compare both identifiers with the offered unit label.

02 Compare the actual unit

Obtain current label, connection and mounting photos. Have the maintenance team compare the offered item and revision with the installed equipment.

03 Establish the applicable procedure

Use the Honeywell instructions applicable to the exact installed item. This checklist does not assign processor, communication, voltage or terminal specifications.

04 Record the accepted identity

Retain the complete marking, revision and comparison photographs with the service record. Resolve identity or connection differences before installation.

Reference basis: Product identity follows the supplied order reference. Offered condition is seller-confirmed.

Other Honeywell listings

Honeywell 51195153-902

Honeywell 51195153-005

Honeywell 51195153-001

Navigation only; no replacement, compatibility or included-accessory relationship is implied.

Apter Power | Product enquiries

sales13@apterpower.com | +86 18030235313

Prepared by Apter Power. Not a manufacturer-issued manual.