KJ4001X1-BE1 12P0818X072 VE4050S2K1C0

Eight-Position I/O Interface Carrier Assembly

Emerson KJ4001X1-BE1 12P0818X072 VE4050S2K1C0 is a horizontal eight-position I/O interface carrier for DeltaV M-series hardware.

KJ4001X1-BE1 12P0818X072 VE4050S2K1C0 configuration dashboard

Modular I/O expansion

Eight keyed positions extend the DeltaV LocalBus without changing the control database architecture.

Structured shield management

The carrier shield bar provides a defined termination point for approved field-cable screens.

Serviceable horizontal layout

Card positions, power connections and carrier boundaries remain visible for controlled maintenance.

Exact order-code identity

Complete order reference	KJ4001X1-BE1 12P0818X072 VE4050S2K1C0
Assembly code	VE4050S2K1C0
Carrier width	8 I/O interface positions
Carrier arrangement	Horizontal M-series I/O carrier
Shield hardware	Carrier shield bar included

KJ4001X1-BE1 12P0818X072 VE4050S2K1C0 is the complete VE4050S2K1C0 carrier reference. Its mechanical frame, connectors and module positions establish the installed DeltaV subsystem relationship and must be treated as an assembly rather than a generic rack.

Eight-Position I/O Interface Carrier Assembly technical capability map

PK Controller recognition	Distinguishes 4-wide and 8-wide carriers
Compatibility boundary	Not physically compatible with S-series controller carriers except through the documented SIS adapter

Installed signal or connection path



System interpretation boundary

Eight I/O positions, carrier shield hardware and the bussed field-power path must be mapped before card removal.

Before exchange, record mounting fasteners, grounding and shield points, every fitted module, carrier-to-carrier connection and the active slot map. Rebuild the approved sequence, then verify power, communications and representative I/O.

Application fit decisions for KJ4001X1-BE1 12P0818X072 VE4050S2K1C0

Eight-card I/O expansion

Add a documented block of eight M-series I/O positions to the controller subsystem.

Field wiring organization

Use keyed terminal blocks and the shield bar to preserve circuit identity.

Horizontal cabinet layout

Maintain airflow, access and extender routing across the installed carrier row.

PK or M-series integration

Apply the controller-specific carrier-count and slot-numbering behavior.

Engineering decision matrix

What must be photographed before removing KJ4001X1-BE1 12P0818X072 VE4050S2K1C0?	Capture the full carrier label, fitted modules, slot order, power and LocalBus connectors, shield landings and mounting hardware.
How should slot identity be retained for KJ4001X1-BE1 12P0818X072 VE4050S2K1C0?	Create a position-by-position record and label each removable module and terminal block before disconnection.
Which compatibility limit applies to KJ4001X1-BE1 12P0818X072 VE4050S2K1C0?	The M-series I/O carrier is not directly interchangeable with S-series controller carriers except in the documented SIS adapter arrangement.
How is field power handled during KJ4001X1-BE1 12P0818X072 VE4050S2K1C0 service?	Isolate the affected sources and record each feed and return before moving carrier wiring.

Applications must be evaluated against the exact installed machine drawing, target, companion hardware and receiving channel. Related product references do not imply substitution.

KJ4001X1-BE1 12P0818X072 VE4050S2K1C0 service controls and maintenance logic

Photograph the complete carrier

Capture KJ4001X1-BE1 12P0818X072 VE4050S2K1C0, every fitted module, connector and mounting point before disassembly.

Remove field and system energy

Isolate all applicable supplies and confirm the cabinet is safe before moving carrier hardware.

Label every interconnect

Mark LocalBus, extender, power, shield and grounding connections at both ends.

Protect connector pins

Prevent contamination, bending and side load while modules and cables are removed.

Restore the original topology

Rebuild carrier order, slot positions and grounding exactly as approved.

Verify the subsystem

Check supply rails, controller communications, carrier diagnostics and representative I/O before release.

Additional technical questions

What grounding evidence is needed for KJ4001X1-BE1 12P0818X072 VE4050S2K1C0?	Record chassis bonding, shield-bar connections and cabinet earth continuity, then verify them after reassembly.
How should extender connections be treated on KJ4001X1-BE1 12P0818X072 VE4050S2K1C0?	Preserve exact cable routing, connector orientation and carrier sequence; never force or cross-connect LocalBus extensions.
What inspection is required before fitting modules to KJ4001X1-BE1 12P0818X072 VE4050S2K1C0?	Inspect connector pins, keying, hold-down points and the carrier surface for damage or contamination.
What proves KJ4001X1-BE1 12P0818X072 VE4050S2K1C0 is ready for service?	Stable power rails, controller communication, correct slot recognition, clean diagnostics and representative I/O checks must all pass.

Technical notes

Exact execution	VE4050S2K1C0 eight-position I/O interface carrier with shield bar
Topology boundary	Carrier width, extender arrangement and controller slot behavior must match the installed design
Technical reference	Emerson DeltaV M-series I/O Subsystem Horizontal Carriers Product Data Sheet, January 2024

KJ4001X1-BE1 12P0818X072 VE4050S2K1C0 source record and supported references

Exact carrier execution

Field-power arrangement	Bussed field power with individual card connections
Controller carrier limit	Maximum 8 total 4-wide or 8-wide carriers
M-series slot behavior	Eight consecutive I/O positions

Eight-position installed slot map

Position	Installed module	Position	Installed module	Terminal / acceptance notes
1	_____	5	_____	_____
2	_____	6	_____	_____
3	_____	7	_____	_____
4	_____	8	_____	_____

Manufacturer reference	Emerson DeltaV M-series I/O Subsystem Horizontal Carriers Product Data Sheet, January 2024
Applicability	Facts are limited to the exact order-code selections and stated matched-system conditions.
Public page	Exact product page linked from the first-page model title
Evidence boundary	No neighboring-model option or unsupported lifecycle conclusion is assigned to this product.

Verified related product references and contact

Recommended product	Emerson KJ3222X1-BA1 12P2532X122 VE4033S2B1
Recommended product	Emerson KJ3203X1-BA1 12P3270X032 VE4001S2T2B4
Recommended product	Emerson KJ1501X1-BC3 12P3935X032 VE5009
Recommended product	Emerson PR6424/01 CS CON021
Recommended product	Emerson PR6423/00R-111-CN CON041

Discuss the exact marking and installed relationship with Apter Power.
sales13@apterpower.com | +86 18030235313