DSQC541 3HAC14363-1

Robot Controller Computer Backplane

ABB DSQC541 3HAC14363-1 is a robot controller computer backplane for the ABB S4Cplus robot controller computer unit.

DSQC541 3HAC14363-1 configuration dashboard

Computer-board interconnect

The backplane carries the physical slot and bus relationships used by the S4Cplus computer unit.

Connector-condition sensitivity

Bent pins, contamination or cracked solder joints can affect multiple boards and startup stages.

Old-to-new article traceability

The DSQC541 record is checked against the related earlier backplane article before replacement.

Exact order-code identity

Complete product reference	DSQC541 3HAC14363-1
Manufacturer	ABB
Product type	Robot Controller Computer Backplane
Primary article number	3HAC14363-1
System family	ABB S4Cplus robot controller computer unit
Manufacturer designation	DSQC541
Board role	Computer backplane
Legacy related article	3HAC3617-1

ABB identifies 3HAC14363-1 as the DSQC541 computer backplane. The user-supplied “-01” form is normalized to the manufacturer article “-1”.

Robot Controller Computer Backplane technical capability map

Installed relationship	Hosts and interconnects controller computer boards	**Replacement basis**	Slot pattern, connector condition and article number
Replacement basis	Complete marking and installed interface	**Supply condition**	New, original product

Installed signal or connection path

Field signal > **Termination block** > **DSQC541 3HAC14363-1** > **LocalBus** > **Control strategy**

System interpretation boundary

Because multiple computer boards share the backplane, a fault can appear as several board or startup alarms. Inspect supply distribution and connector condition before replacing individual boards.

Map every slot, spacer, cable and fastener before removal. After rebuild, verify correct seating, supply rails, controller recognition and startup diagnostics in sequence.

Application fit decisions for DSQC541 3HAC14363-1

S4Cplus computer-unit rebuild

Restore the documented board order and interconnect path during controller overhaul.

Multi-board fault isolation

Evaluate shared power and connector faults when several computer boards report problems.

Backplane damage inspection

Check pins, sockets, solder joints, contamination and mechanical distortion.

Installed-base spare matching

Use the exact article and slot geometry rather than a visual backplane comparison.

Engineering decision matrix

Why is the published model DSQC541 3HAC14363-1 instead of 3HAC14363-01?	ABB documentation uses the article form 3HAC14363-1; the leading zero is not part of the manufacturer number.
What should be mapped before removing DSQC541 3HAC14363-1?	Record every board position, connector, spacer, cable, grounding point and fastening location.

How can DSQC541 3HAC14363-1 create several controller alarms at once?	Shared backplane power or interconnect faults can affect multiple installed computer boards.
Which earlier article is associated with DSQC541 3HAC14363-1?	The DSQC541 backplane is associated with earlier article 3HAC3617-1 in installed-base references.

Applications must be evaluated against the exact installed machine drawing, target, companion hardware and receiving channel. Related product references do not imply substitution.

DSQC541 3HAC14363-1 service controls and maintenance logic

Capture the complete identity

Photograph every character of DSQC541 3HAC14363-1, its revision suffix and the installed position before removal.

Control stored energy

Apply the approved isolation procedure and prove the affected circuits safe before disconnecting hardware.

Label every interface

Mark plugs, terminal conductors, slot position and companion hardware at both ends.

Protect contacts and boards

Use clean ESD-safe handling and prevent bent pins, contamination, side load and unsupported cable weight.

Restore the documented arrangement

Reproduce the original slot, orientation, connector seating, grounding and cable route.

Prove the restored function

Verify power, diagnostics and representative channel or controller behavior before handover.

Additional technical questions

What inspection is essential for DSQC541 3HAC14363-1?	Inspect all pins and sockets, the board surface, solder joints and mechanical flatness under ESD control.
Can board positions be changed while servicing DSQC541 3HAC14363-1?	No. Restore the documented slot order unless an approved ABB modification explicitly changes it.
What measurements help diagnose DSQC541 3HAC14363-1?	Compare backplane supply rails and continuity using the approved procedure before connected boards are blamed.
What proves DSQC541 3HAC14363-1 has been restored correctly?	All boards seat correctly, controller recognition is complete and startup diagnostics are clean.

Technical notes

Exact identity	DSQC541 3HAC14363-1; article 3HAC14363-1

System boundary	Verify the installed ABB S4Cplus robot controller computer unit configuration and every mating interface before exchange
Technical reference	ABB Robotics After Sales Catalog and applicable ABB controller documentation

DSQC541 3HAC14363-1 source record and supported references

Manufacturer reference	ABB Robotics After Sales Catalog and applicable ABB controller documentation
Applicability	Facts are limited to the exact order-code selections and stated matched-system conditions.
Public page	Exact product page linked from the first-page model title
Evidence boundary	No neighboring-model option or unsupported lifecycle conclusion is assigned to this product.

Verified related product references and contact

Recommended product	ABB DSQC406 3HAC035301-001
Recommended product	ABB DSQC604 3HAC12928-1
Recommended product	ABB DSQC608 3HAC12934-1
Recommended product	ABB DSQC611 3HAC13389-2
Recommended product	ABB DSQC652 3HAC025917-001

Discuss the exact marking and installed relationship with Apter Power.
sales13@apterpower.com | +86 18030235313