

APTER POWER INSTALLATION & VERIFICATION REFERENCE

39ACM24BAN 16139-76/09

A separate model-specific field checklist

Use this reference to verify the exact Siemens component before installation, substitution, or recommissioning. It intentionally does not repeat unconfirmed values.


Manufacturer	Siemens
Prepared by	Apter Power
Document ID	AP-SIE-09-39ACM24BAN-16139-76-09-IV-R1
Revision	R1
Issue date	2026-08-14

APTER POWER SALES TEAM

INDUSTRIAL AUTOMATION PRODUCT SUPPORT

Protect the controller baseline before exchanging the BAN-marked assembly.

WHATSAPP / PHONE +86 180 3023 5313
EMAIL sales13@apterpower.com
WEBSITE www.apterpower.com



SCAN FOR PRODUCT & QUOTE
39ACM24BAN 16139-76/09

1. Pre-Installation Verification

Step	Check	Required evidence
1	Identity	Match every character of 39ACM24BAN 16139-76/09 to the physical label; record revision and serial data.
2	Host system	Confirm rack, slot, CPU/drive/controller, firmware, project, and machine-builder approval.
3	Electrical	Verify supply, signal type, channel limits, grounding, shielding, and connector pinout from the exact Siemens document.
4	Mechanical	Confirm form factor, keying, mounting, clearances, cable routing, and environmental limits.
5	Lifecycle	The exact 39ACM24BAN revision was not found in the reviewed public Siemens lifecycle appendix. Treat it as legacy APACS+ hardware and confirm status from Siemens and the nameplate. The 16139-76/09 relationship still requires physical-nameplate confirmation.
6	Commissioning	Apply the original test procedure and record results before returning the equipment to service.

Product-Specific Precautions

- Photograph the complete 39ACM24BAN 16139-76/09 nameplate and PCB revision
- Archive the APACS+ project and all affected channel or network records
- Do not infer electrical data from another 39ACM24BAN assembly marking
- Verify rack, connector, firmware, and field circuit before insertion
- Complete a model-specific functional test before returning the process to service

2. Commissioning Record

Record item	Site entry
Physical model / MLFB	
Serial or revision	
Host system / machine	
Rack / slot / location	
Firmware / project backup	
Connector and wiring verified	
Functional test result	
Technician / date	

Source Basis

Siemens APACS+ lifecycle documentation for the ACM family and the physical 39ACM24BAN nameplate. Physical nameplate verification is required for the additional 16139-76/09 marking.

Important Notice

This Apter Power checklist is not a Siemens installation instruction. The current Siemens documentation, the physical nameplate, the host-equipment manual, and applicable safety rules control all work.

APTER POWER SALES TEAM

INDUSTRIAL AUTOMATION PRODUCT SUPPORT

Protect the controller baseline before exchanging the BAN-marked assembly.

WHATSAPP / PHONE +86 180 3023 5313

EMAIL sales13@apterpower.com

WEBSITE www.apterpower.com



SCAN FOR PRODUCT & QUOTE

39ACM24BAN 16139-76/09