



6.2 Block diagram with recommended connection

6.2.1 Converters: 15A to 125A



6.2.2 Converters: 210A to 280A



6.2.4 Converters: 450A to 850A with a 1-phase fan

