

51198947-100

Application and Configuration Guide | Process Manager Power Supply

Honeywell 51198947-100 is a Version 2 silver power supply for the Process Manager installed base. Honeywell identifies it as a process-manager power supply in its xPM maintenance guidance.

Application features

- Process Manager power-system role
- Version 2 silver power-supply identification
- xPM installed-base maintenance context
- Battery-backup maintenance relevance

Use and configuration

The supply operates as part of the installed Process Manager power system. Its use depends on the cabinet configuration, redundant supply arrangement, battery backup and site maintenance procedure.

Pre-use verification

1	Schedule the work under the approved Process Manager power-maintenance procedure.
2	Record the power-system and battery-backup condition before disturbing the supply.
3	Confirm the 51198947-100 identity and the cabinet's redundant-supply arrangement.
4	Complete wiring, alarm and functional checks before restoring the system.

Important Notice: Verify the 51198947-100 label, cabinet power-system arrangement, backup-battery condition, alarm contacts, grounding and approved maintenance procedure before replacement.

Official source

[Open the directly related official Honeywell PDF](#)

Honeywell System HINTS - October 2025

APTER POWER SALES TEAM

Product support: sales13@apterpower.com
Website: www.apterpower.com
Model: 51198947-100